



Ref no.	Date	Location	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action
202402_RIW2_1	7/2/2024	F	pH	8.6	6.6-8.4	6.5-8.5	<p>Possible reason: Natural variation in water quality due to unknown sources or rainfalls in the vicinity of the water quality monitoring station.</p>
			DO(mg/l)	9.0	5.8	5.5	
			Turbidity	94.3	24.4	32.7	
			SS (mg/L)	83.4	17.0	23.8	<p>Action taken/ to be taken: Repeated in-situ measurement had been conducted immediately to confirm the exceedances. The construction activities conducted at the time was checked with the Contractor.</p>
							<p>Remarks/ Other Observations: Site checking was conducted after the in-situ monitoring and it was noted that water discharge from the site drainage system was not observed at the site area discharge points. Since sudden rainfalls were recorded during and before the monitoring time, the exceedance was potentially related to the temporary increase of road surface runoff.</p> <p>The Contractor is reminded to ensure the wastewater treatment facility is operating properly to avoid any potential project related exceedance.</p>