



Lam Environmental Services Limited

Service Contract No. EDO/01/2017  
Environmental Team for Development of Anderson Road Quarry Site  
Road Improvement Works  
Summary for Notification of Exceedance

Ref no.	Date	Location	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action
X_21RIW2_086	8-Sep-21	F	Turbidity (NTU)	22.9	24.4	32.7	Investigation of the exceedance is still in progress and will be reported in next EM&A report.
			pH	6.8	6.6-8.4	6.5-8.5	
			SS (mg/L)	23.5	17.0	23.8	
			DO(mg/l)	8.7	5.8	5.5	
X_21RIW2_087	17-Sep-21	F	Turbidity (NTU)	64.2	24.4	32.7	Investigation of the exceedance is still in progress and will be reported in next EM&A report.
			pH	8.3	6.6-8.4	6.5-8.5	
			SS (mg/L)	39.7	17.0	23.8	
			DO(mg/l)	8.7	5.8	5.5	
X_21RIW2_088	20-Sep-21	F	Turbidity (NTU)	30.9	24.4	32.7	Investigation of the exceedance is still in progress and will be reported in next EM&A report.
			pH	8.4	6.6-8.4	6.5-8.5	
			SS (mg/L)	31.6	17.0	23.8	
			DO(mg/l)	8.8	5.8	5.5	
X_21RIW2_089	23-Sep-21	F	Turbidity (NTU)	297.1	24.4	32.7	Investigation of the exceedance is still in progress and will be reported in next EM&A report.
			pH	8.4	6.6-8.4	6.5-8.5	
			SS (mg/L)	233.0	17.0	23.8	
			DO(mg/l)	6.4	5.8	5.5	