



Ref no.	Date	Location	Parameters (Unit)	Measured	Action Level	Limit Level	Follow-up action
X_18RIW3_004	18-Feb-19	I	Suspended Solid	300 mg/L	172.8 mg/L	201.4 mg/L	<p><b>Possible reason:</b> Natural variation or changes of water quality in the vicinity of water abstraction location for the water quality monitoring station.</p> <p><b>Action taken/ to be taken:</b> Checking with contractor for the construction activities conducted on 18 February 2019 and review previous monitoring data for the trend of variation.</p> <p><b>Remarks/ Other Observations:</b> Rainfall was recorded during the day of water quality monitoring. No major construction activity was conducted (only survey at RIW3) and no surface run-off was observed surrounding Station I on 18 February 2019. In view of the above, the exceedance was considered not related to project works. In addition, no exceedance was recorded on the subsequent monitoring on 20 February 2019.</p>