

Ref. No.	Date	Time	Location	Construction Noise Level, dB(A)	Parameter	Action Level	Limit Level dB(A)	Follow-up action	
X_N005	28-Dec-20	15:07	NMC05 - G/F, Hong Wah Court Block B Yee Hong House	77	Leq(30-min)	when one documented complaint was received.	(5	Possible reason:	Drilling works at the edge of the slope with partially coverage of noise barrier at the slope of Lin Tak Road
								Action taken / to be taken:	Repeat measurement to confirm result and reviewed the trend of noise measurement. Analysis of contractor's working procedure. Additional monitoring was conducted on 29 December 2020 and no exceedance was recorded.
								Remarks / Other Obs:	The investigation is still undertaken, and would be reported in next monthly report.